

STC-01Z (KH-01)

Steppermotor Controller



Useful for:

- Roboticized bag machine controller;
- Roboticized cut machine controller;
- Powder packing machine controller;
- Others stepper motor monospindle controller you want to use

Content

Chapter one: System characteristic -----	(2)
Chapter two: the front view-----	(2)
Chapter three: The picture of the behind-----	(3)
Chapter four: Conection sketch map-----	(4)
Chapter five: Function flow chart -----	(4)
Chapter six: Parameter setup-----	(6)
Chapter seven: Program edit and instruction explain -----	(7)
Chapter eight: Manual operative method-----	(9)
Chapter nine: automatic performance method-----	(9)
Chapter ten: size of view and size of installation -----	(10)
Chapter eleven: Programme and example of application:	
Example one to six:understand instruction-----	(11)
Example seven:Roboticized bag machine controller-----	(14)
Example eight:Roboticized cut machine controller -----	(15)
Example nine:Powder packing machine controller-----	(16)
Instruction table-----	(17)
Key-press table -----	(17)
Parameter table -----	(18)

Chapter one system characteristic

- l **count of axes:** monopodium;
- l **characteristic of instruction:** random programmable (Can carry out various complications movement: Fixed position control and Not fixed position control) ;
- l **Tallest output frequency:** 40 KHz (specially suit subdivision driver) ;
- l **distinguishability of the output frequency:** 1Hz;
- l **size of program:** maximum is 99;
- l **input point:** 6 (photocoupling) ;
- l **output point:** 3 (photocoupling) ;
- l **displacement range:** -7999999 ~ +7999999;
- l **work status:** Manual running status、 automatic running status、 programme edit status、 parameter setup status;
- l **curve of rising/falling speed:** 2 (optimization) ;
- l **display function:** 8 bits led display, manual / auto status display、 moving / stop status display、 step count / count value / program display、 edit program, parameter display、 input / output status display、 CP pulse and direction display;
- l **auto running function:** programmable, control startup and stop under auto-running state by key-press and level on the port.
- l **manual running function:** allow adjusting the position (manual inch speed and inch step are setuped) ;
- l **parameter setup function:** allow setuping start-up frequency、 curve of riseing/falling speed、 reverse clearance、 manual length、 manual speed、 interrupt jump line number and return zero speed;
- l **edit program function:** allow randomly inserting、 deleteing and modify program。 With jump line number、 the data judge zero、 number of sentence beyond maximum or over minimum test function;
- l **return zero function:** can bothway auto return to zero;
- l **set of program instruction:** total is fourteen;
- l **exterior operation function:** allow executing exterior interrupt operation by setuping parameter and programing turn on /off the A port and the B port.;
- l **power supply:** AC220V (power supply error $\leq \pm 15\%$) 。

Chapter one: front view

The picture of the before (chart1) contain:

- 1. eight bits LED display;
- 2. six show lamp of input state;
- 3. three show lamp of output state;
- 4. show lamp of CP pulse signal;
- 5. show lamp of DIR direction;
- 6. key-press: total 10 key, and most are multifunction, that have different function in different state ,in introduce one function of them deputy one key-press name 。



chart1 the picture of the before

chapter three:the picture of the behind

and introduce of signal

the picture of the behind (chart2) connect port, contain:

- 1. CP、DIR、OPTO connect control line of stepper motor driver This three port connect corresponding ports of driver:
CP-----pulse signal
DIR-----rotation direction signal
OPTO----share+ port for CP OPTO.
State of CP、DIR have corresponding show lamp。
- 2. 启动 startup program , is equivalent to key 启动 on the control panel。
- 3. 停止 pause program that is auto running, is equivalent to 停止 on the control panel, If startup again,program continue to run。
- 4. A 操作 and B 操作 this is characteristic of the controller: Usually to stepper motor, we carry on fix quantify and fix position control, Such as control the electrical engineering circulates the certain to move the quantity with the certain speed, this way is solved very easily, needing to

启动	START SHAPHON	CP
停止		DIR
A操作		OPTO
B操作		输出1
输入1		输出2
输入2		输出3
COM+		~220V
COM-		~220V

Chart 2: picture of behind

program the speed and the displacement only then, but there is a lot of control that are not confirmed beforehand. For example, a stepper motor orders to start circulating toward a direction from the start point, until it runs into a route of travel switch, then again the opposite side returns to the start point. Again, for example, request the electrical engineering between two routes of travel switches, the back and forth circulates the N times. In these examples, we do not know the displacement that the stepper motor circulates in advance, how do we edit the program? This controller resolved into this problem by "interrupt", this controller established two independent "interrupt", we call it as "the A operation" and "the B operation". as "the A operation" as an example, workflow is:

when the program is running, the "A operation" port has signal of input. the stepper motor reduces the speed until stop. program is interrupted at this line. and remember the coordinate value at the interrupt. program jumps to the entrance address of program of the "A operation".

输入 1 和 输入 2 input port of current switch。

5. 输出 1 、 输出 2 和 输出 3 output port of current switch。
6. COM+ 、 COM- output, input port of external power supply, power supply is DC12V/0.3A, COM+ is +, COM- is -, this power supply is provided by the controller。
7. ~220V input port of controller's power supply。

Interface circuit of input signal and output signal :

This controller's "startup", "stop", "A operation", "B operation", "input1", "output2" are input signals, they have the same interface circuit of input. "output1", "output2", "output3" are output signals, they have the same interface circuit of output. for the sake of assurance that there is no mutual interference inside and outside of controller

both input and output circuit have the photocoupling, interior power supply (+5V) and exterior power supply are mutual independence, there two power supplies is provided by independent transformer in the controller.

The state of input signal and output signal have show lamp in the panel correspondingly. for input signal, low level (switch closed) lamp turn on, whereas lamp off; for output, when output is 0, level is low, lamp off, whereas lamp on




Chart 3: switch value

- F connect switch, input low level (0 level), Show lamp is on in the panel, define 0; vice versa
- F for startup, stop, A, B operation, the moment of connection is valid




Chart 4: switch value

- F output low level, in the out port, loader is connected, show lamp is on in the panel, define 1 vice versa

F the current electric of loader not >100mA, whereas need extra power supply

Chapter four --controller connection sketch map




Chart 5: controller connecting sketch map

Chapter five Function flow chart:

controller have four running status: auto status、manual status、program edit status、parameter setup status。 After Electrify or press **复位**, controller is under auto waiting state and coordinate bene place zero point, by now can startup program auto run or switch over manual status, parameter setup status and program edit status only switch over under manual state。 After Edit program finished or parameter setup finished, press **退出** ket.return to manual state (auto saved program)。 At manual state , if you want to switch over edit program state, please press **编辑** key, want to switch over parameter setup state, please press **编参** key 2second more。

(note: key- press **编参** **编辑** **退出** are the same key-press actually, is composite of three key, when introduce one function, use one key-press name , same followed)




Chart 6: Function flow chart

chapter six edit parameter :

the way that pass in and out the parameter setup is : under the manual state, press the

编参 key 2 second more, till pass in the parameter setup。 After finish setuping parameter, press key,return **退出** manual state (parameter is saved auto)。

Parameter have two line, first line display parameter name, second line display parameter data。

The way of modify parameter: when pass in the parameter setup state, first line display **JF** **- - - - -**, and two bit in front of line is parameter name,that is twinkling; if press **^** **v**, the line display before/behind parameter name。 if press **回车** key, pass in the state of edit parameter at the second line, by now first bit of data is twinkling, if press **^** **v**, data is changed。 press **<** **>** key, turn to the next bit。 After modify the data, press **回车** confirm,or press **取消** quit the modification。

In a word, setup parameter by means of pressing **^** **v** **<** **>** **取消** **回车** six keys-press: cursor is moved to corresponding bit by pressing left and right key, led is twinkling, press up and down key, modify the data; press the enter key ,pass in the state of modify parameter, after modify the parameter, press the enter again for acknowledgement and quit press cancel key ,quit and not saved。 Please consult 《operat flow table》。

sn	name	State of display	Rang of data(unit)	Explanation of parameter
1	Start frequency	JF- - - - - JF XXXXX	400 -39999 (Hz)	If the data is low 400Hz,the system warn,user can setup different data, according as the needing of user
2	Curve of rise/fall	rS- - - - - rS X	L、 H (line)	There is two curves in the controller,L is slow; H is quick。 Select different curve according as the practical situation
3	Clearance compensation	CC- - - - - CC XXXX	0 -9999 (count of pulse)	Commonly be used for compensate transfer mechanism(master screw ,gear),error that reverse compensation bring and displacement that is compensated are not displayed in the controller
4	Manual increment	HL- - - - - HLXXXXX X	1 -999999 (pulse)	Under manual state, this is displayment of steppermotor when manual operation,if data is zero,system warn。
5	Manual speed	HF- - - - - HF XXXXX	1 -39999 (Hz)	Under manual state, this is speed f steppermotor when manual operation.if data is zero,system warn
6	Speed of return zero	bF- - - - - bF XXXXX	1 -39999 (Hz)	Speed of return zero when return zero opterion.if data is zero,system warn
7	Entrance address of A operation	nA- - - - - nA XX	00 -99 (line NO)	when the program is running,the “A operation” port has signal of input.the steppermotor reduct the speed till stop.program is interrupted at this line.and remember the coordinate value at the interrupt.program jump entrance address of program of the “A operation”。
8	Entrance address of B operation	nB- - - - - nB XX	00 -99 (line number)	when the program is running,the “B operation” port has signal of input.the steppermotor reduct the speed till stop.program is interrupted at this line.and remember the coordinate value at the interrupt.program jump entrance address of

				program of the “B operation”
9	Mode of pulse	CP----- CP X	0、1	CP=0 is single pulse, CPport output pulse DIR output direction of power level int the behind panel. CP=1 is double pulse.CP port output pulse of plus direction,DIR output minus pulse.

Chapter seven Program edit and instruction explain :

the way that pass in and out the state of program edit is: under manual state , press **编辑** key。 When finish editing program, press **退出** ,return manual state (parameter is saved auto)。

The maximum load of the controller program is 99 rows, every line have a line number that is set automatically, begin to set from 00,if you insert or delete some lines, the line number will be set again automatically。






format of program is : every program have two line (except program has no parameter) , the first line display line number and instruction name , second line display data of instruction。 The last line of program is END

in a word , edit program by means of pressing **▲** **▼** **<** **>** **插入** **删除** **回车** **取消**

eight keys; cursor is moved to corresponding bit by pressing left and right key, led is twinkling, press up and down key, modify the data; press the enter key ,pass in the state of modify parameter, after modify the parameter, press the enter again for acknowledgement and quit press cancel key ,quit and not saved. Please consult 《operation flow table》 .

Explanation of edit program



Edit parameter	Operation Step
enter the edit state	Under manual state, press 编辑 。
quit the edit state	Under edit program state , press 退出 , return manual state , program is saved automatically。
clear the program	Under edit program state, press 清程 2 second more, press till that the 00 line is END。
Input program	<p>first of all clear the program, there is only one line program, that is NO 00 line is END。 Then press 插入 key , NO.00 line instruction change to PAUSE, and is twinkling; press ▲ ▼ , instruction name is changing ; till find to instruction you need, then press 回车 ,pass in the data area (for no data program, after press enter,finish inputing the program), modify data by pressing up and down key, press enter after set data, complete the line program 。 could look at the next line change to END, press 插入 key again, use the same means to input program, till all program is completed 。the new means that input program is that insert the program before the END。</p> <p>Special note: when input new program, there is very accurate program, system warn , the error come forth in the jump instruction : such as JUMP 、J-BIT、J-CNT。 If the line number</p>

	that jump to is greater than this line ,as a result the line of jump to is not input, the system warn. For avoid the case, when input program, demand that the line number of jump to is replace by 00,after complete the program,modify the line number of jump to .
Modify program	Consult the way of “input program” , modify program。
insert program	When the line is twinkling , press  key, before this line,insert a new line.and then edit the new line.
delete program	When the line is twinkling, press  this line is deleted , the programs that is behind of this line are go up。
browse program	When the line is twinkling, press   , could browse the all program.but you want to browse the parameter of the program,please press  , once, then the parameter is twinkling one second

Explanation of instruction (HH—line number , XXXXXXX—data)





S N	instruction	Mode of display	Explanation
1	Pause	HH_PAUSE No parameter	Program pause , waiting for one of them are startup key,startup signal,A operation ,and B operation
2	Displacement	HH_G-LEN ±XXXXXXX	When execute this instruction; steppermotor is running according as the newest speed, displacement,start frequency, Curve of rise/fall, Clearance compensation. If no SPEED before this instruction,then startup frequency is default; the first bit of parameter is symbol bit.0 is plus,- is minus Range of parameter: -7999999 ~ +7999999 unit: count of pulse; If the data is 0,the system warn.
3	Speed	HH_SPEED XXXXXX	The programs that is behind of this instruction are running according as this speed.until the new speed is set. Range of parameter: 1 ~ 39999 unit: pulse/second (Hz); If the data is 0,the system warn.
4	delay	HH_DELAY XXXXXXX	Delay time; Range of parameter: 1 ~ 7999999 unit: millisecond; If the data is 0,the system warn.
5	Unconditional jump	HH_JUMP XX	Unconditional jump , parameter XX figure the line number jumped to ; If the XX number is greater than the number of END , the system warn.
6	loop	HH_LOOP XX XXXXX	Loop from this line to appointed line;two bit in front is line number(low than this line) , last five bit is count of loop (define 0 is infinite) 。 When appointed line is greater than this line , the system warn.

STC01Ztype stepper motor controller


S N	instructio n	Mode of display	Explanation
7	Goto some line	HH_GOTO ± XXXXXXX	Program run to the appointed line, usually , the line is system reference point. The first bit is symbol , plus define that appointed line locate plus direction of zero、 minus define that the line locate minus direction of zero; if parameter=0, define retrun zero; Range of parameter: -7999999 ~ +7999999 unit: count of pulse.
8	Output	HH__OUT XXXX	Three bits in front of paramter define out1~3.every bit has 3 option: 0、 1、 N: 0 ----is high level, load do not turnon, the show lamp off; 1 ----is low level , load turnon, the show lamp on; N ----holding the last state. The last bit is design for buzzer specially: 0 ----when execute the line , buzzer give forth short blast; (note: after the blast is end execute the next line) 1 ---- when execute the line , buzzer give forth long blast; (note: after the blast is end execute the next line) N ---- when execute the line,the buzzer don't work.
9	Jump for Detect bit	HH_J-BIT XX X X	Two bits in front is the line number,that define jump to the address ,the fifth bit is one of both IN1 and IN 2;the eighth bit is condition of jump(0/1);when detected input is condition is set,jump to the appointed line,whereas execute sequentially .
10	Jump for count	HH_J-CNT XX XXXXX	Two bits in front is line number,that the program jump to.the last five bits is data.when the counter is greater than the data,the program jump to the appointed line, whereas execute sequentially. If the line number is greater than the END number , system will warn.
11	Variable Displaceme nt	HH_GO-AB ±X	The mode of instruction function is the same as, HH_G-LEN ±XXXXXXXX, dissimilarity is the displacement is not constant, but a variable , that brought by interrupt , when the newest interrupt happened, the stepper motor droop speed and stop, then the coordinate value is the variable, because the controller has A operation and B operation , in the eighth bit A、B respectively denote variable of A and B, C variable denote the remainder displacement of the displacement instruction is interrupted,when the newest interrupt happens, the variable have symbol, the seventh bit is symbol bit, 0 denote sameness of parameter and variable, -denote opposition of parameter and variable.
12	Counter +1	HH_CNT-1 No parameter	The instruction is related to counter, the controller have a counter, capacity is 999999, the counter value can be displayed under counter state at real time; if power is off the counter value is not saved, unless you press the counter save  . after the controller startup, the last saved value is writed in the counter.the instruction execute operation that counter add 1.
13	Clear counter	HH_CNT-0 No parameter	The instruction is related to counter; Clear the counter.besides the instruction, that press the clear counter key-press  can clear the counter, under the auto state.
14	Clear coordinate	HH_CLR	After execute the instruction,coordinate value and display of the value is changed to zero.the stepper motor regard the point is new zero point.

S N	instructio n	Mode of display	Explanation
15	end	HH__END No parameter	Program is end line,when program execute the line,controller end all program auto,and return waiting state. The instruction is the last line all the times



chapter eight manual mode :




under the auto state,press  could pass in the manual state, the two bit in front display  , denote that is under manual state.press  or  stepper motor is running according as the different direction, the displacement value and speed are set by HL and HF under the manual state, please consult “chart 6:controller operation flow chart” .

Chapter nine auto-running mode :

After the controller startup or reset,clear coordinate auto,and regard the point as the new zero point, the last saved counter value is writed in the counter.and then waiting.press  or input the startup signal,the controller circulates from the 00 line to the END,the program is end, the controller return the waiting state. please consult “chart 6:controller operation flow chart” .








under auto state,there are three sub-states.:

1. waiting state: the control is ready for running, press  or input the startup signal, startup program.when program is end .controller is under the waiting state.
2. auto running state: the controller is running.
3. auto stop state: when the controller is running,press  or input stop signal from port,program is interrupted, the program is waiting for startup signal again.

Under auto state, there are three different modes of display : (switch the display by pressing   )

1. mode of step display:display the coordinate at real time ,unit : pulse counter;
2. mode of counter display: display the value of the counter, unit :number;
3. mode of program display: display the program and it's name at real time.

For distinguish three sub-states and three display states, we distinguish them from others by means of that the two bits in front displaye different words : (followed chart)

display	state	Explanation
	Mode of coordinate display ,under waiting state.	The last six bits display coordinate,(contain symbol bit),if the coordinate is beyond the six bits,only display the last six bits of coordinate .
	Mode of count display,under waiting state	The last six bits display counter. If the counter value is beyond the six bits, only display the last six bits of value.
	Mode of program display,under waiting state	The last six bits display program,the third and forth bits display the line number,the fifth is empty,the sixth,seventh,eighth bits display short name of instruction. (consult 《instruction table》)
	Step,counter,program thress modes of display Under running state	under the running state the two bits in front ind three modes of display is same,  denote that the program is running.
	Step,counter,program thress modes of display	The two bits in front is twinkling  denote that the

Under stop state

program stop.and is waiting for the startup.

Chapter ten size of view and size of installation :

The controller use the flush type appearance' crust, small volume ,light weight (500g), panel in front is 96mm×96mm, length is 122mm, consult the behind chart :




Chart 7: size of view and size of installation

Chapter eleven: Programme and example of application

Example one

Program request: Start frequency 2.5KHz, Curve of rise/fall use H, Clearance compensation is 0;

Circulate request: run 98765 step at 2.9Khz speed, then run in contrary direction 8765 step at 15 KHz speed, and stop.

List of parameter (modify them under the state of setup parameter) JF=02500, rS=H, CC=0000.

List of program : (under the state of edit program)

```

00  SPEED  02900      ; set speed is 2.9KHz
01  G-LEN  00098765   ; steppermotor run in forward direction 98765 step.
02  SPEED  15000      ; set speed is 15 KHz
03  G-LEN  -0008765   ; run in contrary direction 8765step
04  END              ; program is end.
    
```

Example two

Program request: Start frequency 2.5KHz, Curve of rise/fall use L, Clearance compensation is 12;

Circulate request: when startup the buzzer give forth short blast,then run 1234567 step at 39 KHz speed, the

three output are holding 101. delay 55.9s, the last two output are 11, program pause, until startup again. The stepper motor is running at the same speed to the point of another side 888 step. When arrive at the point, buzzer give forth long blast.

List of parameter: (modify them under the state of setup parameter) JF=02500, rS=L, CC=0012.

List of program: (under the state of edit program)

```

00  OUT  nnn0          ; buzzer give forth short blast.
01  SPEED  39000       ; set speed is 39KHz
02  G-LEN  01234567    ; run in forward direction 1234567 step.
03  OUT  101n         ; three output is 101
04  DELAY  0055900     ; delay 55.9s
05  OUT  n11n         ; the last two output is 11
06  PAUSE                      ; program pause
07  GOTO  -0000888     ; return another side 888step.
08  OUT  nnn1         ; long blast
09  END                ; end

```

Example three

Circulate request: (overleap parameter setup) there is a thing, that run 100 step from zero at 2.9KHz speed (the point is reference point); stop at the reference point and output 010; detect input port, if IN1=0, stepper motor return zero. if IN1≠0, the stepper motor run 10000 step at 15 KHz speed, then short blast for warn; return the reference point at 35 KHz speed. If then IN1=0, return zero, whereas continue to loop the first mode, request: return zero, long blast for alarm

List of program: (under the state of edit program)

```

00  SPEED  02900       ; set speed is 2.9KHz
01  G-LEN  00000100    ; run in forward direction 100 step
02  OUT  010n         ; output is 010
03  J-BIT  10  1  0    ; detect state of IN1, is 0, return zero.
04  SPEED  15000       ; if IN1≠0, set speed is 15KHz
05  G-LEN  00010000    ; run in forward direction 10000 step again
06  OUT  nnn0         ; short blast.
07  SPEED  35000       ; set return reference point speed is 35 KHz
08  GOTO  00000100     ; return reference point at speed 35KHz
09  LOOP  03  00000    ; ending loop, until detect IN1=0, then return zero.
10  SPEED  02900       ; return zero speed is 2.9KHz
11  GOTO  00000000     ; return zero
12  OUT  nnn1         ; long blast for alarm
13  END                ; end.

```

Example four

Circulate request: (overleap parameter setup) some thing is running from zero at 39KHz, until encounter the switch in front, then return zero at the same speed, end. (in the system Start frequency is 500Hz, distance from

zero to switch is greater than 100000, and shorter than 100010)

Program analysis: the displacement is not an accurate value, is in a range (belong to variable control). We resolve the problem by the interrupt operation. Connect the switch to port of A operation. Because stepper motor falls the speed and stop. If run to the switch at high speed only, give forth overshoot certainly, for avoid overshoot, run at high speed in advance and then run at low speed, (lower than the Start frequency)

Set parameter: (modify them under the state of setup parameter) set entrance address of 0A operation is nA=04.

List of program: (under the state of edit program)

```

00  SPEED  39000      ; set speed is 39kHz.
01  G-LEN  0099000    ; run at high speed, but not encounter the switch.
02  SPEED  00400      ; the speed is lower than Start frequency
03  G-LEN  07999999   ; set a long displacement to encounter switch.
04  SPEED  39000      ; entrance of A operation, re turn zero speed 39KHz
05  GO-AB  -A         ; in contrary direction, run the same displacement, return zero
06  END                ; end

```

Example five

Circulate request: (overleap parameter setup) something make the reciprocate between the two switches (A--B). Distance of between A\B is greater than 100000 step, is short than 100010, start point is random (but move to A first), after loop 800 times, stop A, buzzer sound long blast for end. Counter display the loop time, speed is 20 KHz, Start frequency is 500Hz.

Program analysis: because the start point is zero point, suppose from zero to B is + direction, from zero to A is - direction, the example is the same as four belong to variable control.

Set parameter: (modify them under the state of setup parameter) set entrance address of 0A operation is nA=03, set entrance address of B operation is nB=09, overleap other parameter.

List of program: (before execute the program, set the mode of counter display)

```

00  CNT-0                ; clear counter
01  SPEED  00400         ; set speed is 400Hz (< Start frequency 500Hz, for avoid overshoot)
02  G-LEN  -7999999      ; move to A at low speed, untill encounter switch A.
03  CNT-1                ; entrance of A, counter add one.
04  J-CNT  00 800        ; loop time reach 800 times, transfer; if no reach 800, execute the next
instruction.
05  SPEED  20000         ; speed 20KHz
06  G-LEN  0099000       ; run to B at the 20KHz
07  SPEED  00400         ; the low speed is lower than Start frequency
08  G-LEN  07999999      ; be about to arrive B, encounter B at the low speed.
09  SPEED  20000         ; entrance of B, speed 20KHz
10  G-LEN  0099000       ; move to A at 20KHz speed
11  SPEED  00400         ; the low speed is lower than Start frequency
12  G-LEN  07999999      ; be about to arrive A, encounter A at the low speed
13  OUT    NNN1          ; loop time reaches 800 time, buzzer sound long blast
14  END                ; end

```


Example six: STC01Z controller control two driver of motor at no same time

Circulate request: the two steppermotor are running at not same time, 1# steppermotor move 7777 step at 7KHz speed, stop and wait 1s, 2# steppermotor move 8888step at 8KHz speed, stop .after 5s both return zero at 9KHz speed ,program is over.

Program analysis: because both are working at not same time,we can switch CP pulse by the single-pole double-throw relay if demand to switch quickly, could select the electronic switch. Regard ouput port (DC12V) as control port.

Set parameter: (overleap set parameter)

sketch map:



List of program:

```

00  OUT    0NNN    ; switch CP to 1# (the example regard OUT1 as switch control)
01  SPEED  07000   ; 1#run at speed 7KHz
02  G-LEN  7777    ; 1# move 7777step
03  OUT    1NNN    ; switch CP to 2#
04  DELAY  1000    ; delay 1s
05  SPEED  08000   ; speed of 2# is 8KHz
06  G-LEN  8888    ; 2# move 8888 step
07  OUT    0NNN    ; switch CP to 1#
08  DELAY  5000    ; delay 5s
09  SPEED  09000   ; the common speed is 9KHz
10  G-LEN  -7777   ; 1# return zero first
11  OUT    1NNN    ; switch CP to 2#
12  DELAY  0500    ; delay 0.5s (the time is relay switch time )
13  G-LEN  -8888   ; 2# return zero
14  END                ; end

```

Example seven: STC01Z-----advanced Roboticized bag machine controller

System scheme:STC01Z controller、two-phase steppermotor 130BYG250A (or three-phase130BC3100A)、driver SH-2H130MH (orSH-3F130MH)、apolegamic AC220V isolating transformer ,perimeter of clamping roller200mm.

Besides STC01Z, 1.there is a valid/invalid key-press(self locking key-press): when press the key,the steppermotor is startuped, when the key is up,even if there is a photoswitch signal, the steppermotor do not run. 2.printing/fixed length key-press(self locking key-press):when down,is printing,when up ,is fixed length.


Circulate request: for example of bag length 500mm, under fixed length mode,startup each time, move 500mm

at high speed,under fixed length mode,startup each time ,move 480mm at high speed, then search color sign at low speed. stop when find color sign. if move to 510mm, do not find still the color sign, judge that is fault, stop and warn at once (short blast 100 times) .demand to sound the long blast 10 times to warn,when produce 50000.at the time clear the counter, take count over again.

There are clear counter key and save counter key ,use them at any moment.

Program analysis: for example of two-phase steppermotor, work under 20 subdivision state. The step angle is 0.09° , pulse count: 20CP pulse/mm.

Set parameter: (under the set parameter) JF=1000, rS=H, CC=0, HL=10, HF=1000, bF=1000, nA=12, nB=00



note: The procedure that we provide may disaccord your request, But we would be free to design the procedure and the hardware that you be satisfied with for you!

List of program: (before startup, pass in the mode of count display)

00	J-BIT	18	1	1	; if the valid/invalid key is invalid(not down,IN1=1),return
01	SPEED	28000			; suppose the high speed is 28KHz
02	J-BIT	05	2	0	; if the <u>printing/fixed</u> length key is down (mode of printing, IN2=0) ,jump to line 5.
03	G-LEN	10000			; under the fixed length state, steppermotor move 500 mm (10000step)
04	JUMP	12			; jump to line 12
05	G-LEN	9600			; under the printing state, motor move 480 mm (9600step) at high speed
06	SPEED	1000			; suppose the speed search the color sign is 1KHz
07	G-LEN	600			; search the color sign at low speed, if find it ,jump to entrance address of A operation
08	OUT	NNN0			; move to 510mm, still find the color sign, short blast to warn (100times)

```

09  DELAY  200          ; delay 0.2s
10  LOOP   07  100      ; short blast 100 times
11  JUMP   18          ; jump to end
12  CNT-1          ; entrance address of A operation, find the color sign, motor stop, counter

```

add one

```

13  J-CNT   15  50000    ; if the counter =50000, jump to 15 line
14  JUMP   18          ; if the counter <50000, jump to end
15  OUT     NNN1        ; long blast to warn (10 times)
16  DELAY  200          ; delay 0.2s
17  LOOP   07  10      ; long blast to warn10times
18  END                      ;end

```

Example eight STC01Z-----advanced Roboticized cut machine controller

System scheme: STC01Z controller、 two-phase steppermotor 130BYG250A (or three-phase130BC3100A)、 driver SH-2H130MH (orSH-3F130MH)、 apolegamic AC220V isolating transformer ,perimeter of clamping roller200mm.

Besides STC01Z, 1.there is a valid/invalid key-press(self locking key-press): when press the key,the steppermotor is startuped, when the key is up,even if there is a photoswitch signal, the steppermotor do not run.


Circulate request: for example of length of cut paper 500mm,startup each time, move 500mm at high speed demand to sound the long blast 10 times to warn, when produce 50000.at the time clear the counter, take count over again.

There are clear counter key and save counter key ,use them at any moment.

Program analysis: for example of two-phase steppermotor, work under 20 subdivision state. The step angle is 0.09°, pulse count: 20CP pulse/mm.

Set parameter: (under the set parameter) JF=1000, rS=H, CC=0, HL=10, HF=1000, bF=1000, nA=00, nB=00

Set this parameter based on the frondose cut machine



note: The procedure that we provide may disaccord your request, But we would be free to design the procedure and the hardware that you be satisfied with for you!

List of program: (before startup, pass in the mode of count display)

```

00  J-BIT   09  1  1    ; if the valid/invalid key is invalid(not down,IN1=1),return
01  SPEED   28000      ; suppose the high speed is 28KHz

```

```

02  G-LEN    10000      ; move 500 mm (10000step)
03  CNT-1                    ; counter add one
04  J-CNT    06  50000   ; if the counter=50000, jump to line 6
05  JUMP     09                    ; the counter<50000,jump to end
06  OUT      NNN1        ;long blast to warn (10times)
07  DELAY    200         ; delay 0.2s
08  LOOP     07  10      ; long blast10times
09  END                                ;end



```

Example nine STC01Z-----advanced Powder packing machine controller

System scheme:STC01Zcontroller、 two-phase steppermotor110BYG250A(or three-phase110BC380)、 driver SH-2H110ML/H (or SH-3F110ML/H)、 apolegamic AC120V/AC220V isolating transformer.

Besides STC01Z, 1.there is a valid/invalid key-press(self locking key-press): when press the key,the stepper motor is startuped, when the key is up,even if there is a photoswitch signal, the stepper motor do not run


Circulate request: for example of the speed of principal axis 2 circle/s.the principal axis rotate one circle,the motor is startup once, the motor drive the scroll bar 1 circle in 0.25s. demand to sound the long blast 10 times to warn, when produce 50000 bag.at the time clear the counter, take count over again.

There are clear counter key  and save counter key ,use them at any moment.

Program analysis: for example of two-phase stepper motor, work under 20 subdivision state. The step angle is 0.09° , pulse count: 20CP pulse/mm.

Set parameter: (under the set parameter) JF=1000, rS=H, CC=0, HL=10, HF=1000, bF=1000, nA=00, nB=00

Set this parameter based on the frondose powder packing machine



Note: The procedure that we provide may disaccord your request, But we would be free to design the procedure and the hardware that you be satisfied with for you!

List of program: (before startup, pass in the mode of count display)

```

00  J-BIT    09  1  1    ; if the valid/invalid key is invalid(not down,IN1=1),return
01  SPEED    38000      ;set the speed is 38KHz

```

STC01Ztype stepper motor controller

```











02  G-LEN      4000      ; rotate 1circle (4000step)
03  CNT-1      ; the counter add 1
04  J-CNT      06  50000  ; if the counter=50000, jump to line 6
05  JUMP       09        ; the counter<50000,jump to end
06  OUT        NNN1      ; long blast to warn (10times)
07  DELAY      200       ; delay 0.2s
08  LOOP       07  10    ; long blast10times
09  END                    ;end

```

instruction table:

sn	name	example	Explanation,range and unit	Full name	Short name
1	Pause	00 PAUSE	Program is paused and wait for startup signal	PAUSE	PAU
2	Displacement	01 G-LEN -1234567	Move 1234567step at new SPEED, contrary direction; -7999999 ~ +7999999、pulse	G-LEN	G-L
3	Set speed	02 SPEED 12345	Set the newest speed is 12345 Hz 1 ~ 39999、pulse/s (Hz);	SPEED	SPD
4	Delay	03 DELAY 1234567	delay: 1234567ms 1 ~ 7999999、ms	DELAY	DLY
5	Unconditional jump	04 JUMP 12	Unconditional jump to line 12 00~ 99、line number	JUMP	JAP
6	Loop	05 LOOP 03 12345	从 this line (05) jump to 03 loop12345times 1~99999 (0 define endless)、time (only forward loop)	LOOP	LOP
7	Goto some line	06 GOTO -1234567	Steppermotor move to -1234567 point -7999999 ~ +7999999、pulse (0 return zero)	GOTO	GOT
8	Output	07 OUT 03 01 N 0	Output value :OUT1=0、OUT2=1、OUT3state is constant..buzzer sound short(1=long ,N=no)	OUT	OUT
9	Detect bit And jump	08 J-BIT 19 2 0	If IN2=0 , jump to line 19,the 1、2 bit=line number,5bit=input , 8bit=jump state	J-BIT	J-B
10	Take count And jump	09 J-CNT 20 12345	If counter value ≥ 12345,jump to line 20 0~59999、natural number.	J-CNT	J-C
11	Variable parameter	10 GO-AB -A	The steppermotor circulate:displacement is absolute value of A、direction contrary A ±A、±B、pulse (note: A、B have symbol)	GO-AB	GAB
12	Counter add 1	11 CNT-1	Counter add one (max999999)	CNT-1	CN1
13	Clear counter	12 CNT-0	Counter is zero	CNT-0	CN0
14	Clear coordinate	13 CLR	Coordinate is zero.the point is new zero point	CLR	CLR
15	end	13 END	Program's end line,can't edit,is in the end of program.	END	END

key-press table

Key-press	function	explanation	Under state	Operation guide
	Startup	Startup program Continue to execute program	Waiting state; After run,stop state; Execute PAUSE	Click
	Enter	Confirm parameter edited Confirm program edited	Edit program state; Set parameter state	Click
	Stop	Pause program running under auto; Pause program running under manual	Auto-running state Manual state	Click
	Cancel	Cancel parameter edited Cancel program edited	Edit program state; Set parameter state	Click
	Return zero	Motor return zero(position when startup)	Waiting state; After run,stop state; Manual state	Click
	Clear program	Clear all program	Edit program state	Press 2 second more
	Delete	Delete program	Edit program state	Click
	Auto	Pass in auto state	Manual state;	Click
	Manual	Pass in manual state	Auto-running state	click
	Insert	Insert one line before this line	Edit program state	Click
	Step	Pass in mode of step display	Waiting state	Click
	Counter	Pass in mode of counter display	Waiting state	Click
	Program	Pass in mode of program display	Waiting state	Click
	Edit	Pass in edit program state	Manual state	Click
	Edit parameter	Pass in set parameter state	Manual state	Press 2 second more
	Quit	Return manual state from edit program state or set parameter,and save program and parameter modified	Edit program state; Set parameter state	Click
	left move cursor	Move to left	Edit program state; Set parameter state	Click
	browse program	When browse program,only display line number and program name,want ot see the data of program, please press the key,data is twinkling 1s,then Return	Edit program state	Click
	down move cursor	Move to the next line	Edit program state; Set parameter state	Click
	clear counter	The counter is zero	Waiting state	Click
	right move cursor	Move to right	Edit program state; Set parameter state	Click
	Save counter	Save the value of counter	Waiting state	click
	reset	Reset the scm in the controller		

parameter table :

	name	example	range	unit	Explanation	
1	Start frequency	JF 12345	400 –39999	Hz	According as size of motor and inertia of loader select	JF
2	Curve of rise/fall	rS H	L、 H	Line	L is low,H is fast(optimization)	rS
3	Clearance compensation	CC 1234	0 –9999	Pulse	compensate transfer's reverse clearance	CC
4	Manual increment	HL 123456	1 –999999	Pulse	Under manual state, this is displacement.	HL
5	Manual speed	HF 12345	1 –39999	Hz	Under manual state ,this is speed	HF
6	Speed of return zero	bF 12345	1 –39999	Hz	When Return zero,this is speed	bF
7	Entrance address of A operation	nA 18	00 –99	Line NO	Aoperation (interrupt) , entrance address	nA
8	Entrance address of B operation	nB 18	00 –99	Line NO	B operation (interrupt) , entrance address	nB
9	Mode of pulse	CP 0	0、 1		CP=0is single pulse、 CP=1 is double pulse	CP