

Manual tool change electric spindle

GDZ100-24Z-2.2(220V)

User Instructions

ER20 220V 8.4A

250-400Hz 12000-24000rpm

1.4-1.96Nm 2.2KW(S1) 3.0KW(S6)

Catalog

1.Product overview.....	1
2.Product appearance figure.....	2
3.Product characteristic curve graph.....	3
4.Product technical parameter table.....	4
5.Product installation instructions.....	5
➤ Circulation cooling system instructions.....	5
➤ Air seal (AS)	5
➤ compressed gas air quality requirements.....	5
➤ Running-in program instructions.....	5
➤ Product pipeline interface explanation.....	6
➤ Product power plug defined instructions.....	6
6.Products using precautions.....	7
➤ Product installed process precautions.....	7
➤ Maintain maintenance precautions.....	7
7.Product common malfunctions&method of exclusion.....	8

Product overview

1.This spindle is built-in type spindle motor, built-in three asynchronous motors,by the inverter control.As the spindle has a compact structure,high power, big torque, small vibration, low noise characteristics,so it can achieve high speed,high powe cutting,high precision and high stability operation.


2.The bearing of spindle use grease lubricated angular to contact bearings,can be achieved lifelong lubricating within the life cycle.

3.The spindle use forced cooling mode to cooling motor,front and rear bearings.Coolant flow through the reasonable arrangement cycle watercourse of the spindle body,thus can take the heat generated of the spindle rotation speed, to achieve thermal equilibrium,let spindle temperature within a certain constant value. External cooling device effect: maintaining a constant temperature of the coolant.

5. The tool clamping methods:this spindle is manual tool change spindle, tool Interface is ER20.


GDZ100-24Z-2.2(220V)

Manual tool change electric spindle outline drawing




GDZ100-24Z-2.2(220V)


Manual tool change electric spindle parametric curve graph



Voltage--speed (frequency) curve graph



Power--speed (frequency) curve graph



Torque-- speed (frequency) curve graph

GDZ100-24Z-2.2(220V)

Manual tool change electric spindle technical parameters

Spindle model	GDZ100-24Z-2.2(220V)	Voltage	220V	Electric current	8.4A
Maximum speed	24000rpm	Rated frequency	250Hz	Rated power	2.2KW
Peak power	3.0KW	Rated torque	1.4Nm	Peak torque	1.96Nm
Motor Pole	Pole 2	Rated speed	15000rpm	Maximum frequency	400Hz

Technical parameters

No.	project	Standard
1	Spindle blowing dust/seal gas pressure(MPa)	0.15-0.2
2	Spindle gas seal gas flow (L/min)	65±10(When on Working)
3	Cooling water pressure (MPa)	≅ 0.25
4	Cooling water flow (L/min)	≅ 3.0
5	Cooling water temperature(°C)	24-28
6	Spindle static state pulse (μm)	≅ 3
7	Spindle vibration (mm/s)	≅ 0.8
8	Spindle diameter (mm)	Φ100 (0/-0.02)
9	Motor windings Pressure test (V/M)	1500V/1 minute withstanding Voltage test
10	Tool Interface	ER20
11	ER collet clamping range	Φ1-Φ13
12	Inverter Specifications	3.0KW (220V)
13	Fitment	For castings, aluminum, glass, etc., and other processing

Spindle installation explanation

1. Circulating Cooling System Description

The system must ensure that the cooling water temperature of supply spindle is between 24-28°C. Usually setting the flow switch in return pipe of the cooling system, to ensure the supply of spindle cooling water. Cooling water requirements: we recommend using distilled water, while recommend Feinuokesi (Fenix) protective agent F1 (using the scale of 1: 200), coolant temperature is 26°C±2°C, inlet, outlet pipe temperature can't exceed 5 °C. It is allowed As long as other monitoring can ensure fuller spindle cooling.

2. Air sealing control

In order to prevent water or impurities enters internal of the spindle, spindle will have gas sealing device, the gas seal machine must be started start with the machine at the same time. And the need to go through multi-stage filtration.

3. Compressed gas quality requirements

The quality requirement of gas which is used in gas seals:

Oil content: < 0.01mg/m³

solid particle: < 5μ m

Pressure dew point: < 7.5°C (0.7MPa)

4. Running-in program instructions


Only all monitoring issued no failures operational signals, at the same time, all safety devices have been installed and working properly, then allow start spindle.

Note: new or spindle which is not used for a long time must to be running slowly. First, start run spindle for half an hour as 25% of the maximum speed, then increase to 50% of the maximum speed, to run 15 minutes, finally, increase to maximum speed. It's need to check the temperature of the spindle during the whole process, spindle will get hot, but not hot hand, if the spindle becomes hot, pls stop the operation and contact our customer service depaGDZent.

5. Product pipeline interface explanation

No.	Function	定义
1	Gas sealing (Protection of impurities into the spindle 0.15-0.2MPa)	Φ6
2	Enter/Out water (Spindle cooling)	Φ8

6. Product power plug defined (WS20)



1—Red—U

2—Black—V

3—Blue—W

4—Yellow & Green—Ground

The usages of the product and warnings

Matters need attention when you install this spindle

1. Before installed, please read this manual carefully, then operate this spindle according to instructions requirements specification;
2. When installed, please carefully, pay attention to personal safety and to avoid injuries occurred during the installed process;
3. Suggest tool used by spindle compliance with IOS1940 specifications dynamic balance level within G1.0.
4. Do not use any tools tapping spindle;
5. Do not use sandpaper and grinding wheel to wipe or grind in axis core and taper hole;
6. Use special removal tool to remove the lock nut and the tool;
7. Untrained personnel can not disassemble and operate electric spindle;

Attention to maintenance and maintenance

1. Electric spindle storage temperature is $20\text{ }^{\circ}\text{C} \pm 10\text{ }^{\circ}\text{C}$, humidity $\leq 85\%$, to allow time to store up to three months;
2. Electric spindle most suitable ambient temperature is $20\text{ }^{\circ}\text{C} \pm 10\text{ }^{\circ}\text{C}$, bearing life can achieve the desired optimum value;
3. The power cord must take waterproof measure, electric spindle housing must be grounded;
4. Electro-spindle must not exceed nameplate parameters;
5. When electric spindle stop, should cut off the power, it must maintain a certain time after spindle completely stopped to wait spindle heat dissipation, then cut off the coolant, If you disable a long time, you need use compressed air, to remove the residual coolant liquid in the cooling pipe.
6. Not allowed to use any mechanical way to forced braking in the shaft;
7. after using the spindle every day, you should wipe spindle taper, then smear with rust oil;
8. Workplace must be clean, there should be strict dust control measures to prevent foreign matter enter the spindle.

Product common malfunctions&method of exclusion

Fault phenomenon	Reason	Method of exclusion
Electric spindle is not running after boot	1、 No inverter power output or set incorrectly	Check that VFD supply three-phase output voltage and setting method
	2、 Spindle plug is not inserted	Check the electrical spindle plug and connection.
	3、 Bad plug connector	
	4、 Bad stator line package	Replace line package
Shutdown after a few seconds of the boot	1、 Electric spindle feed water bad insulation line package	Drying line package
	2、 Electric spindle high temperature cause line package insulation damaged	Replace line package
	3、 Electric spindle lose phase to run,then cause overcurrent protection blackout	Check the electric spindle connection
	4、 Start time is too short	Increase the acceleration time
Electric spindle smoking or the housing hot after a few second of the boot	1、 Inverter output voltage, frequency are not match the use of electric spindle voltage and frequency	Check the VFD and the spindle voltage, frequency
	2、 The VFD is not set correctly	Reset the VFD
Locking nut loose when it is started	Wrong direction of rotation	Change the direction of rotation
Spindle have big noise and vibration	1、 Bearing wear seriously	Replace the bearing
	2、 Precision of parts damaged,it's effect dynamic balance	Calibration of dynamic balance
	3、 Big beat of Spindle	Replace the spindle
Locking nut loose when it is stoped	Stop time is too short	Increase the deceleration time